



Desktop PC Motherboard Replacement

This guide will show the proper steps to remove and replace the computer motherboard.

Written By: David Lennon



INTRODUCTION


The motherboard is the main body of a computer. Over time, computer components degrade and may need to be replaced. Replacing the motherboard can help make a computer run more quickly, smoothly and without errors.



TOOLS:

- [Phillips #2 Screwdriver](#) (1)
 - [All-in-One PC Driver](#) (1)
-

Step 1 — Left Panel



- Remove the two Phillips #2 head 5mm screws from the back side of the computer case.
- ⓘ These screws can be removed by hand.

Step 2



- Next, remove the side panel of the computer case to allow access into the computer.

⚠ If there is a fan mounted on the side panel, make sure to unplug the cable before fully removing the panel.

Step 3 — Right Panel




- Remove two Phillips #2 head 5mm screws from the back side of the computer case.

Step 4





- Next, remove the side panel of the computer case to allow access into the computer.

Step 5 — Graphics Card




- Remove the Phillips #2 head, 5mm screw holding the graphics card in place.
- ⓘ Make sure that you have grounded yourself so that upon removal of the graphics card you do not accidentally shock the circuit board and damage it.

Step 6




- Press the latch on the side of the connector area to unlock the graphics card, and carefully slide the graphics card out from its slot in the computer.
- A good technique is to lay the computer onto its side, push the latch down and lift the graphics card out.

Step 7 — Hard Drive



- Remove two Phillips #2 head 5mm screws holding the hard drive in place.

Step 8




- Remove two Phillips #2 head 5mm screws holding in the other side of the hard drive.

Step 9




- Slide the hard drive out from the metal casing.

Step 10




- Remove the cables from the back of the hard drive.

Step 11 — Motherboard



- Begin to disconnect all cables from the motherboard. Many of the cables will have clips that need to be undone before you can remove them from the motherboard.

Step 12



- Remove eight Phillips #2 head 5mm screws from the motherboard. Be sure to have your computer on its side, so that once the screws are out nothing falls and get damaged.

Step 13



- Double check and make sure all wires and screws have been removed, then carefully remove the motherboard from the computer case.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-09-25 09:23:05 PM.